



| Model | øD [inch] | Doporučený průtok [m ³ /h] | | øD1 [mm] | H [mm] | Hmotnost [kg] |
|---------|-----------|---------------------------------------|---------|----------|--------|---------------|
| | | 1 200µm | 2 500µm | | | |
| PPS1004 | 4 | 80 | 100 | 478 | 520 | 60 |
| PPS1006 | 6 | 150 | 190 | 478 | 670 | 75 |
| PPS1008 | 8 | 300 | 380 | 478 | 870 | 80 |
| PPS1010 | 10 | 500 | 630 | 748 | 790 | 128 |
| PPS1012 | 12 | 700 | 880 | 748 | 970 | 141 |
| PPS1014 | 14 | 1 000 | 1 100 | 1 055 | 1 025 | - |
| PPS1016 | 16 | 1 380 | 1 400 | 1 055 | 1 025 | - |
| PPS1018 | 18 | 1 750 | 2 180 | 1 270 | 1 032 | - |
| PPS1020 | 20 | 2 200 | 2 750 | 1270 | 1 032 | - |

* Doporučený pracovní tlak: 2 - 3bary

** Minimální provozní tlak při proplachu: 1.5bary